2 -

## HISTORIC AMERICAN ENGINEERING RECORD

## Index to Photographs

National Road: Wilson Bridge Spanning Conocoheague Creek on Old Route 40 Hagerstown vicinity Washington County Maryland

HAER No. MD-41

NOTE: These photographs are government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer would be appreciated. All photographs were taken by William Edmund Barrett in 1982 and 1983.

MD-41-1	View of S elevation from 1937 Route 40 Bridge approximately 200 feet downstream.
MD-41-2	Telephoto view of center span of south elevation.
MD-41-3	3/4 view of N elevation showing collapsed arch.
MD-41-4	Closer in view of collapsed arch.
MD-41-5	"
MD-41-6	Detail view of collapsed arch.
MD-41-7	Detailed, telephoto view of collapsed arch.
MD-41-8	II .
MD-41-9	Detailed, telephoto view of collapsed pier showing fill material of spandrel.
MD-41-10	View of bridge roadway, looking W, showing collapsed deck and parapet.
MD-41-11	View of collapsed roadway looking W.
MD-41-12	View of collapsed roadway looking W (vertical orientation).
MD-41-13	View of collapsed roadway looking E.
MD-41-14	View of collapsed roadway showing infill materials.

Wilson Bridge HAER No. MD-41 Index to Photographs Page 2

MD-41-15	View of collapsed roadway (vertical orientation).
MD-41-16	View of damaged parapet wing wall on eastern approach to bridge.
MD-41-17	View of 1937 concrete-arch bridge that replaced Wilson Bridge looking S.